



15 Sullivan Ave., Suite 1W, Liberty, NY 12754 / Phone: 845-295-4000 / Fax: 845-292-8694

Health and Safety Report

District	Location	Project #
Liberty Central School District	White Sulfur Springs School	2526-105
Site Visit Date(s)	Investigation type	Investigator(s)
9/26/2025	Fire Inspection	Gary B. Bowers II NYS DOS #B0320-0007

<u>Executive Summary</u>	1
<u>Project Scope</u>	1
<u>Materials & Methods</u>	1
<u>Results Summary</u>	2
<u>Discussion</u>	2
<u>Comments & Recommendations</u>	2
<u>References</u>	3
<u>Appendix</u>	4



15 Sullivan Ave., Suite 1W, Liberty, NY 12754 / Phone: 845-295-4000 / Fax: 845-292-8694

Executive Summary

The NYS Education Department requires a fire safety inspection to occur, every 11 months, for each public-school facility for which it has issued a certificate of occupancy. A certified code enforcement officer must perform these inspections each year during the period specified by the Commissioner of Education for each region (the schools in Sullivan, Orange, and Ulster Counties are in the Mid-Hudson Region). On Friday, September 26th, 2025, SC BOCES Assistant Health & Safety Coordinator Gary B. Bowers II (NYS CEO #B0320-0007) performed a fire safety re-inspection at the Liberty Central School District's White Sulfur Springs School facility. The fire inspection report can be found in the Appendix to this report. The information from these reports must be submitted through the NYSED Business Portal by a designated school employee. Once this is done the superintendent of schools may certify this submission, at which point the district can print their own 2025-26 certificates of occupancy.

Project Scope

Perform a visual inspection of all school buildings, and complete the fire inspection report. Included in the report to the LCSD are the inspection results and an outline of the submission process.

Materials & Methods

The fire inspection report was completed by a NYS certified code enforcement officer (#B0320-0007) pursuant to the results of the inspections. The Public-School Building Fire Safety Report is prepared by the NYS Education Department, Office of Facilities Planning and available through NYSED Business Portal.



15 Sullivan Ave., Suite 1W, Liberty, NY 12754 / Phone: 845-295-4000 / Fax: 845-292-8694

Results Summary

No environmental monitoring or diagnostic testing was performed during this portion of the investigation.

Discussion

According to the Federal Emergency Management Administration (FEMA), fires kill more than 5,000 Americans each year (more than all natural disasters combined). In addition, over 25,000 people are injured in fires each year, and the annual property loss is estimated at \$18,000,000,000. Recognizing that fire prevention is the number one way to forestall this loss of life and property, the NYS Education Department requires a formal fire safety inspection to be conducted in every public-school building in New York State once every eleven months. This inspection is to be completed by a person certified by the NYS Department of State as a code enforcement official through a process described by the Commissioner of Education.

Comments & Recommendations

The fire safety inspection of facilities at the LCSD's WSS school took place on Friday, September 26th, 2025. The fire inspection report can be found in the Appendix to this report. Information from these reports must be submitted through the NYSED Business Portal by a designated school employee. Once this is done the superintendent of schools must certify this submission, at which point the district can print their own 2025-26 certificates of occupancy.



15 Sullivan Ave., Suite 1W, Liberty, NY 12754 / Phone: 845-295-4000 / Fax: 845-292-8694

References

1. **National Fire Protection Association (NFPA):** NFPA 101 – Life Safety Code. Quincy, MA: NFPA, 2003.
2. **New York State Department of State (NYSDOS):** Fire Code of NYS. Albany, NY: NYSDOS, 2002.



15 Sullivan Ave., Suite 1W, Liberty, NY 12754 / Phone: 845-295-4000 / Fax: 845-292-8694

Appendix

Local Public School Fire Safety Reports

Fire Inspection Site:

Building Name: White Sulfur Springs

Building Use: Daycare

Inspection Date: 9/26/25

Re-Inspection Required: No

Inspector: Gary B. Bowers II

Registration number: B0320-0007

Location	Corrective Action	Code Section	Severity	Re-inspection date
	All violations noted during the initial inspection were resolved on the date of re-inspection. No new violations were noted.			
Total		0		